



# TECHNICAL BULLETIN

---

Cisco Systems, Inc., (formerly Summa Four, Inc.), 25 Sundial Avenue, Manchester, NH 03103

**Technical Bulletin #:** TM-C1-0185A  
**Date Issued:** June 14, 1999  
**Audience:** ISDN Generic Software Users (V4.x and V5.x)  
**Product(s) Affected:** All SDS and VCO Systems  
**Distribution:**  X  - Critical    \_\_\_ - Standard    \_\_\_ - Special

---

## Purpose of Bulletin

The purpose of this bulletin is to notify V4.x and V5.x ISDN generic software users that your VCO or SDS system may stop processing incoming calls in the following situation.

## Situation

The ISDN configuration screen for V4.x and V5.x has an impulse rule field. The default entry for this field is 0. If this field remains at the default of 0, and you receive a setup message on an ISDN span, the resources for call processing will be blocked.

If you suspect that your ISDN spans may receive setup messages, you should assign any impulse rule, other than 0, in the impulse rule field of the span configuration screen. Valid impulse rules for this field are 1 to 254.

See your appropriate ISDN Supplement for instructions on how to create an impulse rule. The following is an example of an impulse rule for handling these incoming setup messages:

```
ISDN RX x  
ISDN TX y
```

```
where x is : SETUP R  
            Process CHAN ID
```

```
where y is: RLS CMPL T  
            IE Cause  
            Data 80A2
```