


Cisco AVVID Solution



IP Telephony
Interoperability of
Cisco CallManager 3.0 (Cisco 3640 Router)
with Fujitsu F9600ES PBX Using T1-CAS

Table of Contents

Summary 3

Test Configuration 3

Test Results 3

 Voice Call Signaling, Call Completion, Voice Path Confirmation 3

 PBX Signaling Interoperability: E&M Immediate-Start 3

 Signaling Interoperability: E&M Wink-Start 4

 PBX Signaling Interoperability: E&M Delay-Dial 4

Equipment Configuration 5

 Cisco Call Manager Configuration 5

 Cisco 3640 Configuration 6

 Fujitsu F9600ES (Rel 13) Configuration 13

List of Figures

Basic Call Setup Configuration 3

Cisco CallManager Configuration 5

Cisco CallManager Route Pattern Configuration 5

Cisco CallManager Gateway Configuration 6

Fujitsu F9600ES Software Configuration 13

Fujitsu Main Clock Status Display 13

Fujitsu Trunk Group Data List 14

Fujitsu Trunk Interface Using Immediate-Start Signaling Type 14

Changing Fujitsu Trunk Signaling Type from Immediate-Start to Delay-Dial 15

Changing Fujitsu Trunk Signaling Type from Delay-Dial to Wink-Start 15

Fujitsu Numbering Plan List 16

Fujitsu MLDT Assignment List 16

List of Tables

PBX Signaling Interoperability: E&M Immediate-Start shows the test results 3

PBX Signaling Interoperability: E&M Wink-Start 4

PBX Signaling Interoperability: E&M Delay-Dial 4



Summary

This document contains the results of Fujitsu (F9600ES, Rel. 13) PBX interoperability testing with T1-CAS signaling on the Cisco 3640 connected to Cisco CallManager 3.0 (1) using an Ethernet link.


The following points should be noted:

- The Fujitsu PBX was set to provide clocking so the Cisco 3640 needs to be set to derive its clock from the incoming DS1 line “line clock”.

Test Configuration

Figure 1 is representative of the various configurations used for testing.

Figure 1 Basic Call Setup Configuration



Test Results

This section presents test cases and results that were used to evaluate the 2MFT T1-CAS on the Cisco 3640.

Voice Call Signaling, Call Completion, Voice Path Confirmation

PBX Signaling Interoperability: E&M Immediate-Start

The objective of this test case is to test the Cisco 3640 Digital T1 interfaces using T1-CAS signaling options on the Fujitsu F9600ES PBX and to test basic call setup functionality between the Cisco CallManager 3.0 (1) and Cisco 3640, and the Fujitsu 9600ES PBX using E&M Immediate-Start, robbed-bit signaling type.

As you begin the test procedure, refer to Figure 1 for the topology used for this test case. Set up the Cisco 3640 Port configuration as shown in Table 1 below. Place a call from the digital phone connected to the PBX on router_B to the IP phone connected to the Ethernet switch and record the results. Verify that the call goes through and that a full-duplex speech path exists between the phones. Repeat this procedure for a call in the other direction (from IP phone to PBX on router_B). Print out a sample of the PBX, Cisco 3640, and Cisco CallManager configurations.

Table 1 PBX Signaling Interoperability: E&M Immediate-Start shows the test results

FUJITSU setting	Cisco 3640 setting	pass/fail	RESULTS
(Tie Trunk, E&M Immediate)	ds0-group 1 timeslots 1-24 type e&m-immediate-start	Pass	No problems dialing through the PBX using this signaling type.

Signaling Interoperability: E&M Wink-Start

The test objective is to test the Cisco 3640 Digital T1 interfaces over the T1-CAS signaling options on the Fujitsu F9600ES PBX and to test basic call setup functionality between the Cisco CallManager 3.0 (1)/3640 and the Fujitsu F9600ES PBX using E&M Wink-Start, robbed-bit signaling type.

To begin the test procedure, refer to Figure 1 for the topology used for this test case. Set up the Cisco 3640 port configuration as listed in Table 2. Place a call from the digital phone connected to the PBX on router_B to the IP phone connected to the Ethernet switch and record results. Verify that the call goes through that a full-duplex speech path exists between the phones. Repeat this procedure for a call in the other direction (from IP phone to PBX on router_B).

Table 2 - PBX Signaling Interoperability: E&M Wink-Start shows the test results.

Table 2 PBX Signaling Interoperability: E&M Wink-Start

FUJITSU setting	Cisco 3640 setting	pass/fail	RESULTS
(Tie Trunk, E&M Wink)	ds0-group 1 timeslots 1-24 type e&m-wink-start	Pass	No problems dialing through the PBX using this signaling type.

PBX Signaling Interoperability: E&M Delay-Dial

The test objective is to test the Cisco 3640 Digital T1 interfaces over the T1-CAS signaling options on the Fujitsu F9600ES PBX and to test basic call setup functionality between the Cisco CallManager 3.0 (1)/3640 and the Fujitsu F9600ES PBX using the E&M Delay-Dial, robbed-bit signaling type.

To begin the test procedure, refer to Figure 1 for the topology used for this test case. Set up the Cisco 3640 port configuration as listed in Table 3. Place a call from the digital phone connected to the PBX on router_B to the IP phone connected to the Ethernet switch and record the results. Verify that the call goes through and a full-duplex speech path exists between the phones. Repeat this procedure for a call in the other direction (from IP phone to PBX on router_B).

The test results are shown in Table 3 - PBX Signaling Interoperability: E&M Delay-Dial.

Table 3 PBX Signaling Interoperability: E&M Delay-Dial

FUJITSU setting	Cisco 3640 setting	pass/fail	RESULTS
(Tie Trunk, E&M Delay-Dial)	ds0-group 1 timeslots 1-24 type e&m-delay-dial	Pass	No problems dialing through the PBX using this signaling type.



Equipment Configuration

Cisco Call Manager Configuration

Cisco CallManager was configured for Software Release 3.0 (1) as shown in the following figures.

Figure 2 Cisco CallManager Configuration



Figure 3 Cisco CallManager Route Pattern Configuration





Figure 4 Cisco CallManager Gateway Configuration



Cisco 3640 Configuration

The listing below provides the configuration of the 3640 router.

Router "B" contains the following hardware:

- 2E2W carrier in slot 0
- NM-HDV carrier in slot 1
- VWIC-2MFT T1 in carrier slot 0
- VOICE 2V carrier in slot 2
- VIC 2FXS in carrier slot 0
- VIC 2FXO in carrier slot 1



```
EUT_B#sh vers
Cisco Internetwork Operating System Software
IOS (tm) 3600 Software (C3640-JS-M), Experimental Version 12.1(20000530:031732)
[liha-v12l_2_xd_throttle.LATEST 104]
Copyright (c) 1986-2000 by cisco Systems, Inc.
Compiled Tue 30-May-00 08:18 by liha
Image text-base: 0x600088F0, data-base: 0x61444000
ROM: System Bootstrap, Version 11.1(7)AX [kuong (7)AX], EARLY DEPLOYMENT RELEASE
SOFTWARE (fc2)
EUT_B uptime is 26 minutes
System returned to ROM by power-on
System image file is "flash:c3640-js-mz"
cisco 3640 (R4700) processor (revision 0x00) with 60416K/5120K bytes of memory.
Processor board ID 05247801
R4700 CPU at 100Mhz, Implementation 33, Rev 1.0
Bridging software.
X.25 software, Version 3.0.0.
SuperLAT software (copyright 1990 by Meridian Technology Corp).
TN3270 Emulation software.
Primary Rate ISDN software, Version 1.1.
2 Ethernet/IEEE 802.3 interface(s)
2 Channelized T1/PRI port(s)
2 Voice FXO interface(s)
2 Voice FXS interface(s)
DRAM configuration is 64 bits wide with parity disabled.
125K bytes of non-volatile configuration memory.
16384K bytes of processor board System flash (Read/Write)
Configuration register is 0x0
EUT_B#
```

EUT_B#sh diag

Slot 0:

```
Combo 2E, 2W Port adapter, 4 ports
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware revision 1.2          Board revision B0
Serial number 7687847         Part number 800-01171-04
Test history 0x0              RMA number 00-00-00
EEPROM format version 1
EEPROM contents (hex):
0x20: 01 1E 01 02 00 75 4E A7 50 04 93 04 00 00 00 00
0x30: 58 00 00 00 98 02 28 17 FF FF FF FF FF FF FF FF
```

Slot 1:

```
High Density Voice Port adapter
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware Revision      : 1.0
Part Number           : 800-03567-01
Board Revision        : B0
Deviation Number      : 0-0
Fab Version           : 02
```

PCB Serial Number : JAB034906LE

```
RMA Test History      : 00
RMA Number            : 0-0-0-0
RMA History           : 00
EEPROM format version 4
EEPROM contents (hex):
0x00: 04 FF 40 00 CC 41 01 00 C0 46 03 20 00 0D EF 01
0x10: 42 42 30 80 00 00 00 02 02 C1 8B 4A 41 42 30
0x20: 33 34 39 30 36 4C 45 03 00 81 00 00 00 00 04 00
0x30: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x40: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x50: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x60: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
0x70: FF FF FF FF FF FF FF FF FF FF FF FF FF FF FF
```

WIC Slot 0:

```
T1 (2 Port) Multi-Flex Trunk (Drop&Insert) WAN Daughter Card
Hardware revision 1.0          Board revision A0
Serial number 19621702        Part number 800-04614-02
Test history 0x0              RMA number 00-00-00
Connector type PCI
EEPROM format version 1
```

EEPROM contents (hex):

```
0x20: 01 24 01 00 01 2B 67 46 50 12 06 02 00 00 00 00
0x30: 50 00 00 00 00 05 20 00 FF FF FF FF FF FF FF FF
HDV firmware: Compiled Fri 05-May-00 10:55 by richc
HDV memory size 524280 heap free 211705
```

Slot 2:

```
4 PORT Voice PM for MARS Port adapter
Port adapter is analyzed
Port adapter insertion time unknown
EEPROM contents at hardware discovery:
Hardware revision 1.0          Board revision B0
Serial number 7968567         Part number 800-02491-01
Test history 0x0              RMA number 00-00-00
EEPROM format version 1
EEPROM contents (hex):
0x20: 01 65 01 00 00 79 97 37 50 09 BB 01 00 00 00 00
```




```
0x30: 58 00 00 00 98 04 01 17 FF FF FF FF FF FF FF FF
WIC Slot 0:
FXS Voice daughter card (2 port)
Hardware revision 1.0          Board revision B0
Serial number 7088068         Part number 800-02493-01
Test history 0x0              RMA number 00-00-00
Connector type Wan Module
EEPROM format version 1
EEPROM contents (hex):
0x20: 01 0E 01 00 00 6C 27 C4 50 09 BD 01 00 00 00 00
0x30: 58 00 00 00 98 01 28 01 FF FF FF FF FF FF FF FF
WIC Slot 1:
FXO Voice daughter card (2 port)
Hardware revision 1.0          Board revision B0
Serial number 7857070         Part number 800-02495-01
Test history 0x0              RMA number 00-00-00
Connector type Wan Module
EEPROM format version 1
EEPROM contents (hex):
0x20: 01 0D 01 00 00 77 E3 AE 50 09 BF 01 00 00 00 00
0x30: 58 00 00 00 98 03 26 01 FF FF FF FF FF FF FF FF
```

EUT_B#

EUT_B#sh controllers t1

T1 1/0 is down.

Applique type is Channelized T1

Cablelength is long gain36 0db

Transmitter is sending remote alarm.

Receiver has loss of signal.

alarm-trigger is not set

Version info Firmware: 20000308, FPGA: 8

Framing is SF, Line Code is AMI, Clock Source is Line.

Data in current interval (49 seconds elapsed):

0 Line Code Violations, 0 Path Code Violations

0 Slip Secs, 49 Fr Loss Secs, 0 Line Err Secs, 0 Degraded Mins

0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 49 Unavail Secs

Total Data (last 2 15 minute intervals):

0 Line Code Violations, 0 Path Code Violations,

0 Slip Secs, 1800 Fr Loss Secs, 0 Line Err Secs, 0 Degraded Mins,

0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 1800 Unavail Secs

T1 1/1 is up.

Applique type is Channelized T1

Cablelength is short 133

No alarms detected.

alarm-trigger is not set

Version info Firmware: 20000308, FPGA: 8

Framing is ESF, Line Code is B8ZS, Clock Source is Line.

Data in current interval (94 seconds elapsed):

0 Line Code Violations, 0 Path Code Violations

0 Slip Secs, 0 Fr Loss Secs, 0 Line Err Secs, 0 Degraded Mins

0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 0 Unavail Secs

Total Data (last 2 15 minute intervals):

0 Line Code Violations, 0 Path Code Violations,

0 Slip Secs, 0 Fr Loss Secs, 0 Line Err Secs, 0 Degraded Mins,

0 Errored Secs, 0 Bursty Err Secs, 0 Severely Err Secs, 0 Unavail Secs

EUT_B#



```
EUT_B#sh conf
Using 1256 out of 129016 bytes
!
version 12.1
service timestamps debug uptime
service timestamps log uptime
no service password-encryption
no service dhcp
!
hostname EUT_B
!
!
!
!
!
!
voice-card 1
!
ip subnet-zero
no ip domain-lookup
ip host whiz 171.69.1.162
ip host dirt 171.69.1.129
ip host danube 171.69.17.14
!
no lane client flush
isdn switch-type primary-qsig
isdn voice-call-failure 0
cns event-service server
!
!
!
!
!
!
controller T1 1/0
!
controller T1 1/1
framing esf
linecode b8zs
cablelength short 133
ds0-group 1 timeslots 1-24 type e&m-immediate-start
!
!
!
interface Tunnell
no ip address
!
interface Ethernet0/0
ip address 10.1.1.7 255.255.255.0
no ip mroute-cache
no cdp enable
!
interface Ethernet0/1
ip address 192.168.71.6 255.255.255.0
no ip mroute-cache
no cdp enable
!
ip classless
no ip http server
!
```

```
no cdp run
!
!
voice-port 1/1:1
!
voice-port 2/0/0
!
voice-port 2/0/1
!
voice-port 2/1/0
!
voice-port 2/1/1
!
dial-peer voice 1 pots
  destination-pattern 5000
  port 2/0/0
!
dial-peer voice 5 pots
  destination-pattern 4...
  port 1/1:1
  prefix 4
!
dial-peer voice 7 voip
  destination-pattern 4003
  session target ipv4:10.1.1.2
  dtmf-relay h245-alphanumeric
  codec g711ulaw
!
!
line con 0
  transport input none
line aux 0
line vty 0 4
  no login
!
end
EUT_B#
```



Fujitsu F9600ES (Rel 13) Configuration

Figure 5 - Fujitsu F9600ES Software Configuration shows the software configuration for the Fujitsu F9600ES.

Figure 5 Fujitsu F9600ES Software Configuration

```
DIS SWFT
                                00-00-02 WED 14:31
*** SERVICE SOFTWARE LIST ***
ALL RIGHTS RESERVED,COPYRIGHT(C)1998 FUJITSU LIMITED
LICENSED MATERIAL PROGRAM PROPERTY OF FUJITSU
LPE2002W E12011622 000 00001% INSTALLED
NAME          TYPE          E/O
DASEP/0120    360507-0    E12011
ATTES         0051E--0    000
IPRCHS        360541-0    000
IPRCHS        360542-0    001
IPCHRS        360555-0    001
IPRCHS        360600-0    001
IPCHRS        360601-0    001
QSCGOS        360974-0    002
END 00-00-02 WED 14:31 (CISCO LAB ES R13)
```

Figure 6 - Fujitsu Main Clock Status Display through Figure 12 - Fujitsu MLDT Assignment List shows the configuration of various signaling types for the Fujitsu F9600ES.

Figure 6 Fujitsu Main Clock Status Display

```
DIS HCLKS
# MAIN CLOCK STATUS DISPLAY #          00-00-02 WED 14:30
< OPERATION STATUS >
  HCLK #0    *
  CH #
< ALARM STATUS >
  HCLK #0    NORMAL
  CH #       TROUBLE
END 00-00-02 WED 14:30 (CISCO LAB ES R13)
```

Figure 7 Fujitsu Trunk Group Data List




Figure 8 Fujitsu Trunk Interface Using Immediate-Start Signaling Type






Figure 9 Changing Fujitsu Trunk Signaling Type from Immediate-Start to Delay-Dial




Figure 10 Changing Fujitsu Trunk Signaling Type from Delay-Dial to Wink-Start




Figure 11 Fujitsu Numbering Plan List

```

Fujitsu - Notepad
DIS NP,,1

# NUMBERING PLAN LIST #                               00-00-01 TUE 14:29 PAGE-001

3110- 1

  DIGIT  EBL  FND  TGH  TGI  AJE  RDD  DBC  TTH  DR  SRH
#
0        1  00
3        30 591 101
40       4  25  0
41       4  25  0
70       30 540 171
71       30 501 101
72       6  591 150
73       30 501 120
74       30 501 129
9        30 001  0
+11     0  72  0
+20     7  130  0
+21     0  015  0
+51     0  72  0
+70     5  090  0
+71     5  090  0
+72     5  090  0
+73     5  090  0
+74     5  090  0
007     4  001  0
030     7  130  0
000     30 000  0

END 00-00-01 TUE 14:30 (CISED LAB ES 010)
  
```

Figure 12 Fujitsu MLDT Assignment List

```

Fujitsu - Notepad
DIS MLDT

# MLDT ASSIGNMENT LIST #                               00-00-01 TUE 14:31 PAGE-001

  BHL  EN  J          TYPE  RSH  FRL  COS  DT  USC  SPRL  PB  HSC  BR
      LA  PP  RP  IP  RP  IT  RB  BR  PS  LT  PDM
      NAME  SMT
#
4100(00000000)      0  2  1  1  1  0  0  2  0  1
      1  1  1  1  1  1  1  1  1  0  0
      '000'  0
#
4101(00000002)     0  2  0  1  1  0  0  2  0  1
      1  1  1  1  1  1  1  1  1  0  0
      '000V'  0
#
4102(00000004)     0  2  1  1  1  1  0  0  0  0  1
      1  1  1  1  1  1  1  1  1  0  0
      'BL TEST 2'  0

END 00-00-01 TUE 14:31 (CISED LAB ES 010)
  
```




Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy Les Moulineaux Cedex 9
France
www.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems Australia, Pty., Ltd
Level 17, 99 Walker Street
North Sydney
NSW 2059 Australia
www.cisco.com
Tel: +61 2 8448 7100
Fax: +61 2 9957 4350

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco.com Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2001 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement. Printed in the USA. Cisco, Cisco IOS, Cisco Systems, and Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries.

All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0102R)