



summafour

TECHNICAL BULLETIN

Summa Four, Inc., 25 Sundial Avenue, Manchester, New Hampshire 03103

Technical Bulletin #: TM-C1-0162
Date Issued: April 15, 1998
Audience: Generic V4.2 Customers
Product(s) Affected: Generic V4.2 FSR00 base through V4.2 FSR00 PUN23
Distribution: ___ - Critical X - Standard ___ - Special

Purpose of Bulletin

Customers who use the enhanced \$67 command on switches running Generic V4.2 FSR00 through V4.2 FSR00 PUN23 may experience system crashes. This was seen only on live switches and was not reproducible on lab systems by Summa Four or by customers.

Corrective Action

This problem has been fixed and has been introduced into the V4.2 Generic at V4.2 FSR00 PUN24. Since the problem could not be reproduced this fix is based on code analysis.