

# **Guide to Cisco Multiservice Switch Documentation (June 2002)**

This guide explains how to access release notes and product manuals for multiservice switching products.

Our products ship with this guide and a Documentation CD. Starting in June, 2002, Cisco multiservice switching products will no longer ship with printed release notes. Instead, release notes are available online or on the Documentation CD. We are making this change to ensure you always get the latest release notes, because printed release notes might be obsolete or outdated.

## To Access or Print Release Notes

Multiservice switch release notes are on the Documentation CD, and are also accessible from http://www.cisco.com/univercd/cc/td/doc/product/wanbu/index.htm. Table 1 lists the June 2002 product release versions and their corresponding release notes.

Table 1 June 2002 Product Release Versions and Release Notes

Switch or Component Description	Release Version	Release Notes	(Online) Release Note Part Number		
CWM (Cisco Wide Area Network Manager)	CWM 11.0	Release Notes for Cisco WAN Manager Release 11 for Solaris 7	OL-2821-01		
BPX and IGX Switch Software	SwSw 9.3.40	Release Notes for Cisco WAN Switching Software, Release 9.3.40	OL-2822-01		
oute Processor Module  RPM/B and RPM-PR: IOS 12.2(8)T4  RPM-XF: IOS 12.2(8)YP		Release Notes for Cisco MGX Route Processor Module (RPM/B and RPM-PR) for MGX Release 1.2.10 and MGX Release 3 Release Notes for Cisco MGX Route Processor Module (RPM-XF) for Release 3 for MGX 8850 (PXM45)	OL-2824-01 OL-2823-01		



Table 1 June 2002 Product Release Versions and Release Notes (continued)

Switch or Component Description	Release Version	Release Notes	(Online) Release Note Part Number		
MGX 8830, MGX 8850 (PXM45), MGX 8850 (PXM1E)	MGX 3.0	Release Notes for Cisco MGX 8850 (PXM45/B and PXM1E) and MGX 8830 Software Version 3	OL-2825-01		
MGX 8230, MGX 8250, MGX 8850 (PXM1)	MGX 1.2.10	Release Notes for Cisco MGX 8230, MGX 8250, and MGX 8850 (PXM1), Software Version 1.2.10	OL-2827-01		
MGX 8950	MGX 3.0	Release Notes for Cisco MGX 8950 Software Version 3	OL-2826-01		
Service Expansion Shelf (SES)	SES 3.0	Release Notes for Cisco SES PNNI Controller, Release 3	OL-2727-01		
Voice Interworking Service Module (VISM); VISM-PR	3.0(0)	Release Notes for Cisco Voice Interworking Service Module Release 3.0(0)	OL-2523-01		



The June 2002 product release includes two new PNNI routing switches: the MGX 8830 and the MGX 8850 (PXM1E). For clarity, the MGX 8850 switch will now be referred to by the type of processor card it uses, for example, MGX 8850 (PXM1), MGX 8850 (PXM1E), or MGX 8850 (PXM45). These new titles will help you access or order compatible documentation. The release notes contain more information about these new switches.

Release notes cannot be ordered, but can easily be printed from the online PDF file. To access release notes online, you need to know the version number (Table 1). Release notes are generally organized as follows: *Switch name*, *Release notes*, *version number*. The following sample procedure describes how to find and print the MGX 8950 Release 3 release notes:

- Step 1 Go to the http://www.cisco.com/univercd/cc/td/doc/product/wanbu/index.htm URL.
- Step 2 Click on MGX 8950.
- Step 3 Click on Release Notes.
- Step 4 Click on 3.0 Version Release Notes for Cisco MGX 8950.
- Step 5 If you click on the PDF icon in the top right corner, you can download the release notes to your hard drive or print them.

# **To Access or Print Product Manuals**

Multiservice switch product manuals are on the Documentation CD. They are also accessible from http://www.cisco.com/univercd/cc/td/doc/product/wanbu/index.htm, and can be printed from the online PDF file. The manuals released in June 2002 are listed in Table 2.

Table 2 Manuals for June 2002 Product Releases

DOC Number	Title	CWM Rel 11	SES Rel 3	RPM	VISM Rel 3	MGX 8230 PXM1 Rel 1.2.10	MGX 8250 PXM1 Rel 1.2.10	MGX 8850 PXM1 Rel 1.2.10	MGX 8830 PXM1E Rel 3	MGX 8850 PXM1E Rel 3	MGX 8850 PXM45 Rel 3	MGX 8950 PXM45 Rel 3
DOC-7814255=	Cisco Frame Relay Software Configuration Guide and Command Reference					1	1	1	х	X		
DOC-7810327=	Cisco Frame Relay Software Configuration Guide and Command Reference for the MGX 8850 FRSM12 Card, Release 3										x	
DOC-7814547=	Cisco MGX 8830 Hardware Installation Guide, Release 3								X			
DOC-7814248=	Cisco MGX 8850 (PXM1E) and MGX 8830 Software Configuration Guide, Release 3								X	X		
DOC-7814577=	Cisco MGX 8850 (PXM45) and MGX 8950 Software Configuration Guide, Release 3										X	X
DOC-7814250=	Cisco MGX 8850 Hardware Installation Guide, Release 3 (PXM45/B and PXM1E)									X	X	
DOC-7814245=	Cisco MGX 8850, MGX 8950, and MGX 8830 Command Reference, Release 3 (PXM45/B and PXM1E)								X	X	X	X
DOC-7814147=	Cisco MGX 8950 Hardware Installation Guide, Release 3											X
online only (OL-2768-01)	Cisco MGX Route Processor Module (RPM-XF) Installation and Configuration Guide, Release 3 for MGX 8850 (PXM45)			x								
DOC-7814260=	Cisco SES PNNI Controller Command Reference, Release 3		Х									
DOC-7814258=	Cisco SES PNNI Controller Software Configuration Guide, Release 3		х									
online only (OL-2521-01)	Cisco VISM Installation and Configuration Guide, Release 3				Х							
DOC-7813542=	Cisco WAN Manager Database Interface Guide, Release 11	Х										
DOC-7813567=	Cisco WAN Manager Installation Guide for Solaris 7, Release 11	х										
DOC-7813569=	Cisco WAN Manager SNMP Service Agent, Release 11	х										
DOC-7813568=	Cisco WAN Manager User's Guide, Release	х										

1.See the "Release Notes for Cisco MGX 8230, MGX 8250, and MGX 8850 (PXM1), Software Version 1.2.10" for details about hardware and software supported in MGX release 1.2.10.

To access manuals online, you need to know the release version number (see Table 1). Online product manuals are generally organized as follows: *Switch name, Release version, Document title*. The following sample procedure describes how to find and print the MGX 8950 Hardware Installation Guide:

- Step 1 Go to the http://www.cisco.com/univercd/cc/td/doc/product/wanbu/index.htm URL.
- Step 2 Click on MGX 8950.
- Step 3 Click on Release 3.
- Step 4 Click on MGX 8950 Hardware Installation Guide.

Step 5

If you click on the PDF icon in the top right corner, you can download the manual to your hard drive or print it.

## To Order Product Manuals

To order manuals, you need to know the DOC number (Table 2). The DOC number includes the = symbol. Manuals with no DOC number are available *online only*.



Printed documentation is shipped separately from your product order.

The way you place an order depends on whether you are a Cisco.com user.

## **Registered Cisco.com Users**

If you are a registered Cisco.com user (Cisco direct customer), you can order documentation from the Networking Products MarketPlace at http://www.cisco.com/cgi-bin/order/order\_root.pl

Additional part numbers for other manuals are available from your local account representative, or by selecting the documentation product family after choosing a Price List at http://www.cisco.com/cgi-bin/front.x/pricing

## **Nonregistered Cisco.com Users**

If you are not a registered Cisco.com user, you can order printed copies of Cisco product documentation through a local account representative by calling Cisco Worldwide Sales at 800 553-NETS(6387).

#### **Documentation CD**

You can sign up to receive the monthly Documentation CD at http://www.cisco.com/cgi-bin/order/order\_root.pl.

#### World Wide Web

You can access the most current Cisco documentation on the World Wide Web at http://www.cisco.com.

#### **Documentation Feedback**

We appreciate any comments you have about your experience finding or ordering product documentation. Please submit your input to http://www.cisco.com/warp/public/732/docsurvey/index.html.

Copyright © 2002 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0201R)